

**TECHNICAL SERVICE BULLETIN
RAFNA RAILGEAR**

**LOCKING CABLE, P/N R-4838
FOR R-290, R-450 RAILGEAR**

ISSUE DATE: December 13, 2005

TSB NUMBER: TSB-168 Rev 0

HAZARD / URGENCY RATING

	DANGER - Physical harm is possible if TBS is not observed or followed
x	WARNING - Equipment damage is possible if TBS is not observed or followed
x	CAUTION - Essential issue affecting operation, service, parts or installation
	INFORMATIONAL - Advisory which may be of interest

APPLICABLE EQUIPMENT:

All vehicles equipped with Rafna Railgear using Locking Cable, P/N R-4838.

SUMMARY:

This Service Bulletin provides instructions on what action needs to be taken for:

- A. Routine cleaning.
- B. Locking Cable replacement.

For Rafna Locking Cable, P/N R-4838.

IMPACT:

Operational, functional and safety issues may arise if the Locking Cable is not routinely cleaned, and or the replacement of Locking Cable, R-4838, is not followed as listed in Action section of this TSB.

ACTION:

Operator of the vehicle should keep Locking Cable clean and make certain that Locking Cable is functioning properly.

If a replacement Locking Cable is required, contact G&B Specialties for replacement part.

Do not purchase after market cable.

G&B Specialties replacement Locking Cables are designed with stainless steel internals for harsh weather conditions.

**TECHNICAL SERVICE BULLETIN
RAFNA RAILGEAR**

**LOCKING CABLE, P/N R-4838
FOR R-290, R-450 RAILGEAR**

ISSUE DATE: December 13, 2005

TSB NUMBER: TSB-168 Rev 0

HAZARD / URGENCY RATING	
	DANGER - Physical harm is possible if TBS is not observed or followed
x	WARNING - Equipment damage is possible if TBS is not observed or followed
x	CAUTION - Essential issue affecting operation, service, parts or installation
	INFORMATIONAL - Advisory which may be of interest

**TECHNICAL SERVICE BULLETIN
RAFNA RAILGEAR**

LOCKING CABLE, P/N R-4838
FOR R-290, R-450 RAILGEAR

ISSUE DATE: December 13, 2005

TSB NUMBER: TSB-168 Rev 0

HAZARD / URGENCY RATING	
	DANGER - Physical harm is possible if TBS is not observed or followed
x	WARNING - Equipment damage is possible if TBS is not observed or followed
x	CAUTION - Essential issue affecting operation, service, parts or installation
	INFORMATIONAL - Advisory which may be of interest

**TECHNICAL SERVICE BULLETIN
RAFNA RAILGEAR**

**LOCKING CABLE, P/N R-4838
FOR R-290, R-450 RAILGEAR**

ISSUE DATE: December 13, 2005

TSB NUMBER: TSB-168 Rev 0

HAZARD / URGENCY RATING	
	DANGER - Physical harm is possible if TBS is not observed or followed
x	WARNING - Equipment damage is possible if TBS is not observed or followed
x	CAUTION - Essential issue affecting operation, service, parts or installation
	INFORMATIONAL - Advisory which may be of interest

**TECHNICAL SERVICE BULLETIN
RAFNA RAILGEAR**

LOCKING CABLE, P/N R-4838
FOR R-290, R-450 RAILGEAR

ISSUE DATE: December 13, 2005

TSB NUMBER: TSB-168 Rev 0

HAZARD / URGENCY RATING	
	DANGER - Physical harm is possible if TBS is not observed or followed
x	WARNING - Equipment damage is possible if TBS is not observed or followed
x	CAUTION - Essential issue affecting operation, service, parts or installation
	INFORMATIONAL - Advisory which may be of interest