

## TECHNICAL SERVICE BULLETIN RAFNA RAILGEAR

ISSUE DA	<b>ATE:</b> July 2, 2007	TSB NUMBER: TSB172		
HAZARD / URGENCY RATING				
Х	DANGER - Physical harm is possible if TSB is not observed or followed			
Х	WARNING - Equipment damage is possible if TSB is not observed or followed			
Х	CAUTION - Essential issue affecting operation, service, parts or installation			
Х	INFORMATIONAL - Advisory which	may be of interest		

## APPLICABLE EQUIPMENT:

G&B Specialties R-290 Railgear Front Bumper Extensions for 2008 Ford F-Series (F250, F350, F450, F550)

SUMMARY:

Use *Loctite Red* when installing fasteners for front frame extensions. (See loctite notes on references drawings TSB172-1 and TSB172-2) For reference only

IMPACT:

Eliminates fasteners from coming loose.


ACTION:

Apply *Loctite Red* on fasteners during assembly as shown on reference drawings TSB172-1 and TSB172-2. For reference only



## TECHNICAL SERVICE BULLETIN RAFNA RAILGEAR

ISSUE D	<b>ATE:</b> July 2, 2007	TSB NUMBER: TSB172		
HAZARD / URGENCY RATING				
Х	X DANGER - Physical harm is possible if TSB is not observed or followed			
Х	WARNING - Equipment damage is possible if TSB is not observed or followed			
Х	CAUTION - Essential issue affecting operation, service, parts or installation			
Х	INFORMATIONAL - Advisory which may be of interest			




**G&B Specialties Inc.** 535 West 3<sup>rd</sup> Street, Berwick, PA, USA Tel: 1-570-752-5901 Fax: (570) 752-6397



## TECHNICAL SERVICE BULLETIN RAFNA RAILGEAR

ISSUE D	<b>ATE:</b> July 2, 2007	TSB NUMBER: TSB172		
HAZARD / URGENCY RATING				
Х	DANGER - Physical harm is possible if TSB is not observed or followed			
Х	WARNING - Equipment damage is possible if TSB is not observed or followed			
Х	CAUTION - Essential issue affecting operation, service, parts or installation			
Х	INFORMATIONAL - Advisory which may be of interest			



**G&B Specialties Inc.** 535 West 3<sup>rd</sup> Street, Berwick, PA, USA Tel: 1-570-752-5901 Fax: (570) 752-6397