

**TECHNICAL SERVICE BULLETIN
RAFNA RAILGEAR**

ISSUE DATE: April 18, 2007

TSB NUMBER: TSB-171 REV A

HAZARD / URGENCY RATING

	DANGER - Physical harm is possible if TBS is not observed or followed
	WARNING - Equipment damage is possible if TBS is not observed or followed
X	CAUTION - Essential issue affecting operation, service, parts or installation
X	INFORMATIONAL - Advisory which may be of interest

APPLICABLE EQUIPMENT:

G&B Specialties R-290 Railgear Cylinders shipped after April 1, 2007.

SUMMARY:

Cylinder R-9115, (sketch attached), has been redesigned with a 90 degree port, and will now have two fittings and the flow reducer installed into this port at factory. This was done to create a more user friendly installation for installers when clearance problem were encountered on certain model vehicles.

IMPACT:

Easier installation

ACTION:

Revised R-9115 can be used for replacement cylinders, and for future installs.

**TECHNICAL SERVICE BULLETIN
RAFNA RAILGEAR**

ISSUE DATE: April 18, 2007

TSB NUMBER: TSB-171 REV A

HAZARD / URGENCY RATING	
	DANGER - Physical harm is possible if TBS is not observed or followed
	WARNING - Equipment damage is possible if TBS is not observed or followed
X	CAUTION - Essential issue affecting operation, service, parts or installation
X	INFORMATIONAL - Advisory which may be of interest

