

**TECHNICAL SERVICE BULLETIN
RAFNA RAILGEAR**

**PUMP ASSEMBLIES FOR R-290 RAILGEAR
PART NUMBERS R-048 AND R-048B**

ISSUE DATE: June 19, 2009

TSB NUMBER: TSB-183 Rev A

HAZARD / URGENCY RATING	
	DANGER - Physical harm is possible if TSB is not observed or followed
X	WARNING - Equipment damage is possible if TSB is not observed or followed
X	CAUTION - Essential issue affecting operation, service, parts or installation
	INFORMATIONAL - Advisory which may be of interest

APPLICABLE EQUIPMENT:

All Rafna R-290 Railgear where R-048 or R-048B, Pump Assemblies are used.

SUMMARY:

All further issues of R-048 and R-048B pump assemblies will now be recommended to have a 200 amp fuse installed to isolate the power supplied to the pump as per print.

IMPACT:

The addition of the fuse assures that in any case of pump or fuse failure, the power supplied to the truck will not fail as well.

ACTION:

For installation, add a 200 amp fuse per drawings EXXXXXR048ICC and EXXXXXR048B.

