

TECHNICAL SERVICE BULLETIN RAFNA RAILGEAR

ISSUE DAT	E: October 31, 2008	TSB NUMBER:	TSB-181	
HAZARD / URGENCY RATING				
	DANGER - Physical harm is possible if TBS is not observed or followed			
	WARNING - Equipment damage is possible if TBS is not observed or followed			
	CAUTION - Essential issue affecting operation, service, parts or installation			
x	X INFORMATIONAL - Advisory which may be of interest			

APPLICABLE EQUIPMENT:

All G&B Specialties R-250HD/R-290 Railgear equipped with ACCURIDE steel wheel part #28680 (RAFNA part #S-201502)

SUMMARY:

The ACCURIDE wheel (#28680) has been discontinued and replaced with ACCURIDE wheel part #50180. The RAFNA part number remains the same (S-201502). The ACCURIDE wheel #50180 is a direct replacement for the ACCURIDE wheel #50180.

IMPACT:

There is no negative impact on vehicle as the new wheel is a direct replacement and is identical in form, fit and function to the old wheel.

ACTION:

None. TSB for informational purposes only.